

Energy Safety Canada is the national safety association for the oil and gas industry. We develop and support common industry safety standards, deliver effective learning systems, share data analysis and safety expertise with workers and employers, and advocate for worker health and safety. Our goal is the same as industry's – zero injuries, zero incidents.

Share and Collaborate / Energy Safety Canada works collaboratively with organizations to develop Safety Alerts that improve hazard awareness and injury prevention. Canada's leading oil and gas industry trade associations support the sharing of information to help companies of all sizes improve safe work performance.

Disclaimer / This document is intended to be flexible in application and provide guidance to users rather than act as a prescriptive solution. Recognizing that one solution is not appropriate for all users and situations, it presents accepted guidance that generally apply to all situations.

While Energy Safety Canada believes that the information contained herein is reliable under the conditions and subject to the limitations set out, Energy Safety Canada does not guarantee its accuracy. The use of this document or any information contained will be at the user's sole risk, regardless of any fault or negligence of Energy Safety Canada and the submitting organization.

Copyright/Right to Reproduce / Copyright for this document is held by Energy Safety Canada, 2019. All rights reserved. Energy Safety Canada encourages the copying, reproduction and distribution of this document to promote health and safety in the workplace, provided that Energy Safety Canada is acknowledged. However, no part of this publication may be copied, reproduced or distributed for profit or other commercial enterprise, nor may any part be incorporated into any other publication, without written permission of Energy Safety Canada.

# EQUIPMENT DAMAGE - TUBING STRING FALLS BEFORE SLIPS LATCHED

## **DESCRIPTION:**

Setting plate on 40-ton MYT elevator found to be broken after string fell 8m. As a result of rapid lifting before the slips were fully set, the pipe collar was dropped onto the slip setting ring, and the full weight of the pipe damaged the elevators.

While only equipment was damaged, this incident could have potentially caused serious injury to rig personnel and damage other equipment.



DAMAGED ELEVATORS, NOTICE INSIDE CONDITION OF ELEVATOR DIES

Page 1 of 2



#### **CAUSE:**

- Slip dies heavily impacted with debris/ice/foreign material.
- Rapid lifting prior to the slips being fully set may have resulted in the pipe being dropped onto the slip setting ring with the full weight of the stand or string impacting the elevator.

## **CONTRIBUTING FACTORS:**

- Lifting string without the slips being fully engaged can transfer weight to setting plate causing the setting ring to fail.
- Overloading or overpulling (example jarring operations); exceeding working load rating; or operations that have induced elevators to high accelerations; or high impact loads could have impact. The elevators should have been pulled out of service as soon as the elevator dies were shown to be worn.
- Y series elevators are to be used with a slip-setting ring in place and correctly sized for the tubular to achieve depression of the slip segments. Using the elevator with an incorrectly sized setting ring or no setting ring can result in damaging the elevator and could result in the pipe being dropped. The slips of Y series elevators will set when the elevator is raised against the tool joint, Collar Box upset, External upset end or load rated lift nubbin which pushes down on the slip-setting ring.

## **CORRECTIVE ACTION:**

- » Make sure all slip segments are free in the "up" position when latching the elevator. If any of the segments are stuck in the down position, the elevator may not close properly.
- » Make sure the elevator and slip bodies are used with the correct size tubular (per API specification). Oversized pipe will cause difficulties such as latching partially or not at all. Undersized or oversized pipe could cause uneven stress distribution, inadequate load bearing area, and possible wedging in the slip setting ring.
- » Inspections, for both end user and service company, be conducted as outlined in CAODC Recommended Practice 4.0 Inspection and Certification of Overhead Equipment <u>https://caodc.ca/files/03\_Recommended\_Practices/RP\_4.0\_Edition\_4\_2016.pdf</u>

#### **Third Party Equipment Corrective Actions:**

- Inspect and ensure all third-party equipment is complete and in good running conditions before sending them out.
- Qualified inspection personnel are to perform non-destructive testing. Load testing may be required as per original equipment manufacturer requirements. Elevators are produced from cast alloy heat-treated steel and must not be welded in the field. Improper welding can cause cracks and brittleness in heat-affected areas which can result in dramatic weakening of the part and possible failure.
- Equipment rental company developed notice to be sent with "Y" series elevators (rental or purchase) as part of the QA/QC certification documentation package. Outlined the importance of care/maintenance and warning against excessive running speeds.

