

## Skandi Caledonia Dropped Object



PSV 2019



#### **Dropped Object (Near Miss) – 10/09/2019**

Statement from Skandi Caledonia: DocMap ID: 30004214




During cargo ops with an installation in the North Sea crane the pennant wire came out of the hook from the installation crane and fell to main deck on the Skandi Caledonia.


The crane came down with an empty hook for the AB's to hook on to an empty mud skip.

As soon as the hook touched the deck the master link jumped out of the main block and fell to the deck 2m from where the 2 AB`S were standing. We were fortunate it didn't fall towards the personnel on deck.











#### **Drops Calculator**

The master link that fell from the hook to deck, had a length of approximately 5m with a weight of approximately 30kg.





### Cause








The rigger onboard the installation did report the defect however they carried on using the crane and failed to check if the gate was closed and locking pin was inserted.

Installation management have ensured training is given to all deck crew on stopping the job and ensuring safety barriers are in place.











Always plan every lifting operation and never walk under a suspended load

# Lesson to be learned here for us is to never assume that an "empty" load/hook is safe to approach!



**DCF**Management

Thank you